


Report No.: FG070913


## Appendix B. Setup Photographs

## <Radiated Emission>

**H Plane** 



Front View




Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YLXEZ801-0801 Page Number : B1 of B3 Report Issued Date: Aug. 17, 2010 Report Version : Rev. 01



Report No.: FG070913



Remote View

## E1 Plane



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YLXEZ801-0801 Page Number : B2 of B3
Report Issued Date : Aug. 17, 2010
Report Version : Rev. 01





Report No.: FG070913

Rear View





Remote View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YLXEZ801-0801 Page Number : B3 of B3
Report Issued Date : Aug. 17, 2010
Report Version : Rev. 01