

Appendix D. Product Photos

Sample A



Sample B



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YLXEZ801-0801 Page Number : D1 of D1
Report Issued Date : Aug. 17, 2010
Report Version : Rev. 01

Report No.: FA070913



Battery 1



Battery 2





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YLXEZ801-0801 Page Number : D2 of D2
Report Issued Date : Aug. 17, 2010
Report Version : Rev. 01

Report No.: FA070913



Report No.: FA070913


Appendix E. Test Setup Photos





Right Cheek









Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YLXEZ801-0801 Page Number : E1 of E1
Report Issued Date : Aug. 17, 2010
Report Version : Rev. 01