1. External Photograph of EUT

Brand Name: VIZIO / Model Name: VHB100

Report No.: EP061724



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100 Page Number : 1 of 26
Report Issued Date : Aug. 06, 2010
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100 Page Number : 2 of 26 Report Issued Date : Aug. 06, 2010

Report No.: EP061724





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100 Page Number : 3 of 26 Report Issued Date : Aug. 06, 2010





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100


Page Number : 4 of 26 Report Issued Date : Aug. 06, 2010




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100

Page Number : 5 of 26

Report Issued Date : Aug. 06, 2010





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100 Page Number : 6 of 26
Report Issued Date : Aug. 06, 2010
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: VIZIO / Model Name: VHB100

Report No.: EP061724

List of Accessory:

Specification of Accessory		
AC Adapter	Brand Name	Phihong
	Model Name	PSM03A-050Q
	POWAR Rating	I/P:100-240Vac, 50-60Hz, 100mA; 6-8VA O/P: 5Vdc, 550mA
Battery	Brand Name	Danionics
USB Cable	Signal Line Type	1.0 meter shielded cable without ferrite core
Audio Cable	Signal Line Type	1.0 meter non-shielded cable without ferrite core

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100 Page Number : 7 of 26
Report Issued Date : Aug. 06, 2010
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100 Page Number : 8 of 26 Report Issued Date : Aug. 06, 2010

Report No.: EP061724

Report No.: EP061724




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100 Page Number : 9 of 26 Report Issued Date : Aug. 06, 2010

Report No.: EP061724



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100 Page Number : 10 of 26
Report Issued Date : Aug. 06, 2010
Report Version : Rev. 01

Report No.: EP061724



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100

Page Number : 11 of 26 Report Issued Date : Aug. 06, 2010



Page Number


Report Version

: 12 of 26

: Rev. 01

Report Issued Date : Aug. 06, 2010

Report No.: EP061724




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100

Report No.: EP061724



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100 Page Number : 13 of 26
Report Issued Date : Aug. 06, 2010



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100 Page Number : 14 of 26
Report Issued Date : Aug. 06, 2010
Report Version : Rev. 01





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YLY-VHB100 IC: 9108A-VHB100 Page Number : 15 of 26
Report Issued Date : Aug. 06, 2010
Report Version : Rev. 01