

# Appendix D. Product Photos

# Sample A



# Sample B



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YMREZONE-B Page Number : D1 of D1
Report Issued Date : Aug. 17, 2010
Report Version : Rev. 01

Report No.: FA070913-01



Battery 1



#### **Battery 2**





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YMREZONE-B Page Number : D2 of D2
Report Issued Date : Aug. 17, 2010
Report Version : Rev. 01

Report No.: FA070913-01



# Report No.: FA070913-01


# Appendix E. Test Setup Photos





**Right Cheek** 

**Right Tilted** 







**Left Tilted** 



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YMREZONE-B Page Number : E1 of E1
Report Issued Date : Aug. 17, 2010
Report Version : Rev. 01