XIAMEN COMFORT SCIENCE & TECHNOLOGY GROUP CO., LTD.

(5/F) NO.168, QIANPU ROAD, SIMING DISTRICT, XIAMEN, CHINA

2019/4/19

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

List of Differences for FCC ID: YMX-EC806A

Location	Old PCB of FCC ID: YMX-EC806A	New PCB of FCC ID:YMX-EC806A
Handrail on the right	Side Board Controller PCBA: PCB:EC806A-Button-V1.0	Side Board Controller PCBA: EC806A-Button-V1.1 , add R22-R23, R24-R28, R18-R21, TVS, C3, C4-C5, ESD1-ESD4
Upper (back) of the mandrel	Core drive plate:	Add material: 1. C60-69, Ceramic capacitor 2.L10, common mode choke 3.C75-80, C122, chip resistor 4.L1-L3, common mode choke delete: 1.CE2, Aluminium electrolytic capacitor 2.R87,187, R88,188, chip resistor 3.FB9-14, Magnetic beads
Seat subordinate	Pedestal adapter plate	delete: 1. Remove R610K Resistance 2. Removal of Q2 5551 triode Add material: Increase ESD1-ESD3
Armrest	USB charging board	Change of USB Charging Board Layout
Back movement	Protract Motor: ZYT-56S-1-2E, DC24V	Protract Motor: ZYT-56S-1-6E, DC24V
	Up-down motor: ZYT-56S-1-4E, DC24V	Up-down motor: ZYT-56S-1-8E, DC24V
Back movement	Knead motor: ZYT-56S-1-3E, DC24V	Knead motor: ZYT-56S-1-7E, DC24V

Sincerely,

XIAMEN COMFORT SCIENCE & TECHNOLOGY GROUP CO., LTD.

Cur Penyfer

Pengfei Cui/ Safety Engineer