
Report No: HK11090844-2

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Model: 13595



INTERTEK TESTING SERVICE

Report No: HK11090844-2

Configuration Photographs

Worst-Case Radiated Emissions

(Back View)

Model: 13595

