

1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : G1 of G7

Report Version : Rev. 01 Project No. : 662420





Side view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : G2 of G7
Report Version : Rev. 01

Project No. : 662420



2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : G3 of G7

Report Version : Rev. 01 Project No. : 662420




For radiated emissions 30MHz~1GHz





Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report Version : G4 of G7

: Rev. 01


Project No.

: 662420




For radiated emissions 30MHz~1GHz





Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report Version : G5 of G7 : Rev. 01


Project No.

: 662420



For radiated emissions above 1GHz





Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : G6 of G7
Report Version : Rev. 01

Project No. : 662420




For radiated emissions above 1GHz

Beamforming



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : G7 of G7

Report Version : Rev. 01
Project No. : 662420