


Test Photos Appendix F

1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F1 of F5

Report Version : Rev. 01 Project No. : 662420



Test Photos Appendix F



Side view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F2 of F5
Report Version : Rev. 01

Project No. : 662420



**Test Photos** Appendix F

# 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F3 of F5 Report Version

: Rev. 01 Project No. : 662420




Test Photos Appendix F

## For radiated emissions 30MHz~1GHz



#### Front view



# Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No.


Report Version : Rev. 01 Project No. : 662420

: F4 of F5




Test Photos Appendix F

## For radiated emissions above 1GHz



### Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No.

Report Version : Rev. 01 Project No. : 662420

: F5 of F5