
Report No.: 13061080HKG-002

## **Equipment Photographs**

Model: OP0118-13

(Internal)





Report No.: 13061080HKG-002

## **Equipment Photographs**

Model: OP0118-13

(Internal)







Report No.: 13061080HKG-002

## **Equipment Photographs**

Model: OP0118-13

(Internal)






Report No.: 13061080HKG-002

### **Equipment Photographs**

Model: OP0118-13

(Internal)






Report No.: 13061080HKG-002

## **Equipment Photographs**

Model: OP0118-13

(Internal)





Report No.: 13061080HKG-002

### **Equipment Photographs**

Model: OP0118-13

(Internal)






Report No.: 13061080HKG-002

### **Equipment Photographs**

Model: OP0118-13

(Internal)





Report No.: 13061080HKG-002

### **Equipment Photographs**

Model: OP0118-13

(Internal)






Report No.: 13061080HKG-002

### **Equipment Photographs**

Model: OP0118-13

(Internal)






Report No.: 13061080HKG-002

### **Equipment Photographs**

Model: OP0118-13

(Internal)







Report No.: 13061080HKG-002

## **Equipment Photographs**

Model: OP0118-13

(Internal)







Report No.: 13061080HKG-002

### **Equipment Photographs**

Model: OP0118-13

(Internal)







Report No.: 13061080HKG-002

## **Equipment Photographs**

Model: OP0118-13

(Internal)





Report No.: 13061080HKG-002

### **Equipment Photographs**

Model: OP0118-13

(Internal)

