INTERTEK TESTING SERVICE

Report No: HK13020622-3

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Model: SMR015



INTERTEK TESTING SERVICE

Report No: HK13020622-3

Configuration Photographs Worst-Case Radiated Emissions

(Rear View)

Model: SMR015

