
INTERTEK TESTING SERVICES

Report No.: HK10080771-1 Sample No.:1/1



Date: 14.0CT.2010 21:54:48

Code: FCC15C_d / Effective Date: 26 Jan 2010