

Report No: CCIS12090016102

7 Test Setup Photo

Radiated spurious emission:





Telephone: +86 (0) 755 23118282 Fax: +86 (0) 755 23116366



Report No: CCIS12090016102

Conducted emission:



Project No.: CCIS120900161RF