


Report No: CCIS12090016101

7 Test Setup Photo

Radiated spurious emission:





Telephone: +86 (0) 755 23118282 Fax: +86 (0) 755 23116366