


page 1 of 2

## ANNEX C INTERNAL PHOTOS



146178\_9.JPG: TNSLR-Q80WD-H1147, PCB top view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F146178E1

 Date of issue:
 10 June 2015
 Order No.:
 14-116178



page 2 of 2

## ANNEX C INTERNAL PHOTOS



146178\_10.JPG: TNSLR-Q80WD-H1147, PCB bottom view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F146178E1

 Date of issue:
 10 June 2015
 Order No.:
 14-116178