

page 1 of 3

ANNEX C INTERNAL PHOTOS



150253_10.JPG: TNLR-Q80L800-H1147, PCB, top view

Test Report No.: F150253E1 Order No.: 15-110253

Examiner: Manuel BASTERT Date of issue: 19 June 2015



page 2 of 3

ANNEX C INTERNAL PHOTOS



150253_11.JPG: TNLR-Q80L800-H1147, PCB, bottom view

Test Report No.: F150253E1 Order No.: 15-110253

Examiner: Manuel BASTERT Date of issue: 19 June 2015



page 3 of 3

ANNEX C INTERNAL PHOTOS



150253_12.JPG: TNLR-Q80L800-H1147, PCB, bottom view, shielding removed

Examiner: Manuel BASTERT Date of issue: 19 June 2015 Test Report No.: F150253E1 Order No.: 15-110253