


page 1 of 6

ANNEX A TEST SETUP PHOTOS



135058_12.JPG: Test setup shielded chamber


Test Report No.: F135058E3 Order No.: 13-115058

Examiner: Manuel BASTERT Date of issue: 27 May 2015



page 2 of 6

ANNEX A TEST SETUP PHOTOS



135058_11.JPG: Test setup fully anechoic chamber (E-Field)

Test Report No.: F135058E3 Order No.: 13-115058

Examiner: Manuel BASTERT Date of issue: 27 May 2015



page 3 of 6

ANNEX A TEST SETUP PHOTOS



135058_10.JPG: Test setup fuly anechoic chamber (H-Field)

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F135058E3

 Date of issue:
 27 May 2015
 Order No.:
 13-115058



page 4 of 6

ANNEX A TEST SETUP PHOTOS



135058_13.JPG: Test setup open area test site

Examiner: Manuel BASTERT Date of issue: 27 May 2015 Test Report No.: F135058E3 Order No.: 13-115058



page 5 of 6

ANNEX A TEST SETUP PHOTOS



135058_4.JPG: Test setup outdoor test site

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F135058E3

 Date of issue:
 27 May 2015
 Order No.:
 13-115058



page 6 of 6

ANNEX A TEST SETUP PHOTOS



135058_14.jpg: Test setup climatic chamber

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F135058E3

 Date of issue:
 27 May 2015
 Order No.:
 13-115058