


page 1 of 3

ANNEX C INTERNAL PHOTOS



135074_13.JPG: TB-M18-H1147, PCB, top view


Test Report No.: F135074E1 Order No.: 13-115074

Examiner: Manuel BASTERT Date of issue: 19 May 2015



page 2 of 3

ANNEX C INTERNAL PHOTOS



135074_14.JPG: TB-M18-H1147, PCB, bottom view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F135074E1

 Date of issue:
 19 May 2015
 Order No.:
 13-115074



page 3 of 3

ANNEX C INTERNAL PHOTOS



135074_15.JPG: TB-M18-H1147, frontal antenna view

Test Report No.: F135074E1 Order No.: 13-115074

Examiner: Manuel BASTERT Date of issue: 19 May 2015