

page 1 of 5

ANNEX A TEST SETUP PHOTOS



153588_1.jpg: Test setup shielded chamber


 Examiner:
 Manuel BASTERT
 Test Report No.:
 F153588E1

 Date of issue:
 12 November 2015
 Order No.:
 15-113588



page 2 of 5

ANNEX A TEST SETUP PHOTOS



153588_2.JPG: Test setup fully anechoic chamber (E-Field)

Test Report No.: F153588E1 Order No.: 15-113588

Examiner: Manuel BASTERT
Date of issue: 12 November 2015



page 3 of 5

ANNEX A TEST SETUP PHOTOS



153588_3.JPG: Test setup fully anechoic chamber (H-Field)


Test Report No.: F153588E1 Order No.: 15-113588

Examiner: Manuel BASTERT
Date of issue: 12 November 2015



page 4 of 5

ANNEX A TEST SETUP PHOTOS



153588_4.jpg: Test setup open area test site

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F153588E1

 Date of issue:
 12 November 2015
 Order No.:
 15-113588



page 5 of 5

ANNEX A TEST SETUP PHOTOS



153588_5.JPG: Test setup outdoor test site

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F153588E1

 Date of issue:
 12 November 2015
 Order No.:
 15-113588