



153143_1.JPG: TN902-Q175L200-H1147, 3-D-view 1

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 15-113143

 page 1 of 4
 15-113143
 15-113143





153143_2.JPG: TN902-Q175L200-H1147, 3-D-view 2

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 15-113143

 page 2 of 4





153143_3.JPG: TN902-Q175L200-H1147, rear view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 15-113143

 page 3 of 4





153143_4.JPG: TN902-Q175L200-H1147, connector view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153143E1

 Date of issue:
 08/26/2015
 Order Number:
 15-113143

 page 4 of 4