


page 1 of 6

ANNEX A TEST SETUP PHOTOS




135074_17.JPG: Test setup shielded chamber

Test Report No.: F135074E3 Order No.: 13-115074



page 2 of 6

ANNEX A TEST SETUP PHOTOS




135074_18.JPG: Test setup fully anechoic chamber (E-Field)

Test Report No.: F135074E3 Order No.: 13-115074



page 3 of 6

ANNEX A TEST SETUP PHOTOS




135074_19.JPG: Test setup fully anechoic chamber (H-Field)

Test Report No.: F135074E3 Order No.: 13-115074



page 4 of 6

ANNEX A TEST SETUP PHOTOS



135074_20a.JPG: Test setup open area test site

Test Report No.: F135074E3 Order No.: 13-115074



page 5 of 6

ANNEX A TEST SETUP PHOTOS




135074_21.JPG: Test setup outdoor test site

Examiner: Manuel BASTERT Date of issue: 27 May 2015 Test Report No.: F135074E3 Order No.: 13-115074



page 6 of 6

ANNEX A TEST SETUP PHOTOS



135074_22.JPG: Test setup climatic chamber

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F135074E3

 Date of issue:
 27 May 2015
 Order No.:
 13-115074