


page 1 of 3

## ANNEX C INTERNAL PHOTOS



150243\_11.JPG: TNSLR-Q350-H1147, PCB, top view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F150243E1

 Date of issue:
 11 June 2015
 Order No.:
 15-110243



## ANNEX C INTERNAL PHOTOS



150243\_12.JPG: TNSLR-Q350-H1147, PCB, bottom view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F150243E1

 Date of issue:
 11 June 2015
 Order No.:
 15-110243
 page 2 of 3



## ANNEX C INTERNAL PHOTOS



150243\_13.JPG: TNSLR-Q350-H1147, PCB, bottom view, shielding removed

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F150243E1

 Date of issue:
 11 June 2015
 Order No.:
 15-110243
 page 3 of 3