


ANNEX B EXTERNAL PHOTOS



135053_5.JPG: TB-Q08-0.15-RS4.47T, overview with cable and plug

Test Report No.: F135053E2 Order No.: 13-115053

Examiner: Manuel BASTERT Date of issue: 27 May 2015



page 2 of 5

ANNEX B EXTERNAL PHOTOS



135053_6.JPG: TB-Q08-0.15-RS4.47T, top view


 Examiner:
 Manuel BASTERT
 Test Report No.:
 F135053E2

 Date of issue:
 27 May 2015
 Order No.:
 13-115053



page 3 of 5

ANNEX B EXTERNAL PHOTOS



135053_7.JPG: TB-Q08-0.15-RS4.47T, bottom view (not grouted, PCB bottom visible)

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F135053E2

 Date of issue:
 27 May 2015
 Order No.:
 13-115053



page 4 of 5

ANNEX B EXTERNAL PHOTOS




135053_9.JPG: TB-Q08-0.15-RS4.47T, S2500 plug

Test Report No.: F135053E2 Order No.: 13-115053

Examiner: Manuel BASTERT Date of issue: 27 May 2015



ANNEX B EXTERNAL PHOTOS



135053_10.JPG: RFID tag

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F135053E2

 Date of issue:
 27 May 2015
 Order No.:
 13-115053
 page 5 of 5