


page 1 of 5

ANNEX B EXTERNAL PHOTOS



150243_7.JPG: TNSLR-Q350-H1147, 3D view 1

Test Report No.: F150243E1 Order No.: 15-110243

Examiner: Manuel BASTERT Date of issue: 11 June 2015



page 2 of 5

ANNEX B EXTERNAL PHOTOS



150243_8.JPG: TNSLR-Q350-H1147, 3D view 2

Examiner: Manuel BASTERT Date of issue: 11 June 2015 Test Report No.: F150243E1 Order No.: 15-110243



page 3 of 5

ANNEX B EXTERNAL PHOTOS



150243_9.JPG: TNSLR-Q350-H1147, top view

Test Report No.: F150243E1 Order No.: 15-110243

Examiner: Manuel BASTERT Date of issue: 11 June 2015



page 4 of 5

ANNEX B EXTERNAL PHOTOS



150243_10.JPG: TNSLR-Q350-H1147, bottom view

Test Report No.: F150243E1 Order No.: 15-110243

Examiner: Manuel BASTERT Date of issue: 11 June 2015



page 5 of 5

ANNEX B EXTERNAL PHOTOS



150243_14.JPG: TAG

Examiner: Manuel BASTERT Date of issue: 11 June 2015 Test Report No.: F150243E1 Order No.: 15-110243