


page 1 of 6

ANNEX A TEST SETUP PHOTOS




135058_12.JPG: Test setup shielded chamber

Examiner: Manuel BASTERT Date of issue: 27 May 2015 Test Report No.: F135058E1 Order No.: F135058



page 2 of 6

ANNEX A TEST SETUP PHOTOS




135058_11.JPG: Test setup fully anechoic chamber (E-Field)

Test Report No.: F135058E1 Order No.: F135058



page 3 of 6

ANNEX A TEST SETUP PHOTOS




135058_10.JPG: Test setup fuly anechoic chamber (H-Field)

Test Report No.: F135058E1 Order No.: 13-115058



page 4 of 6

ANNEX A TEST SETUP PHOTOS



135058_13.JPG: Test setup open area test site

Test Report No.: F135058E1 Order No.: 13-115058



ANNEX A TEST SETUP PHOTOS




135058_4.JPG: Test setup outdoor test site

Test Report No.: F135058E1 Order No.: 13-115058



page 6 of 6

ANNEX A TEST SETUP PHOTOS



135058_14.jpg: Test setup climatic chamber

Test Report No.: F135058E1 Order No.: 13-115058