


ANNEX C INTERNAL PHOTOS



135058_8.JPG: TNLR-Q80-H1147, rear view to PCB

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F135058E3

 Date of issue:
 27 May 2015
 Order No.:
 13-115058
 page 1 of 1