
Test report No.: 31HE0102-SH-04-B


Page : 28 of 29

Issued date : December 2, 2011 Revised date : December 27, 2011 FCC ID : YR7AERODRP2

### **APPENDIX 3: Photographs of test setup**

#### Out of band emissions (Radiated)







## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No.: 31HE0102-SH-04-B


Page : 29 of 29

Issued date : December 2, 2011 Revised date : December 27, 2011 FCC ID : YR7AERODRP2

#### Pre-check of the worst position







# UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401