
Test report No.: 30DE0169-SH-01-B

Page : 12 of 52

Issued date : September 27, 2010 FCC ID : YR7AERODRP1

Spurious Emission (Radiated emission)





UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No.: 30DE0169-SH-01-B


Page : 13 of 52

Issued date : September 27, 2010 FCC ID : YR7AERODRP1

Pre-check of the worst position







UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401