

Test report No. : 11253018S-A-R1
Page : 52 of 53
Issued date : November 7, 2016
FCC ID : YR7SKR3000P6

APPENDIX 3: Photographs of test setup


Radiated Spurious Emission



Rear (Below 1 GHz)



Rear (Above 1 GHz)





UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 11253018S-A-R1
Page : 53 of 53
Issued date : November 7, 2016
FCC ID : YR7SKR3000P6

Worst Case Position

X-axis







End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401