Test report No. : 30DE0169-HO-01-A-R1
Page : 18 of 82

Page : 18 of 82 FCC ID : YR7AERODRP1 Issued date : September 16, 2010 Revised date : October 26, 2010

APPENDIX 1: Photographs of test setup

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 30DE0169-HO-01-A-R1


Page : 19 of 82
FCC ID : YR7AERODRP1
Issued date : September 16, 2010
Revised date : October 26, 2010

1. Photograph of EUT

Front Surface



2. Position of antenna



UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 30DE0169-HO-01-A-R1

Page : 20 of 82
FCC ID : YR7AERODRP1
Issued date : September 16, 2010
Revised date : October 26, 2010

3. Photograph of test setup








UL Japan, Inc. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

: 30DE0169-HO-01-A-R1

Test report No.
Page
FCC ID : 21 of 82 : YR7AERODRP1 : September 16, 2010 : October 26, 2010 Issued date Revised date







UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone Facsimile : +81 596 24 8116 : +81 596 24 8124