Page : 24 of 27

Issued date : October 3, 2012

Revised date : October 22, 2012

FCC ID : YS34D454C2D5003

# **APPENDIX 3: Photographs of test setup**

# **Conducted emission**



Photo 1




Photo 2

#### UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 25 of 27

Issued date : October 3, 2012

Revised date : October 22, 2012

FCC ID : YS34D454C2D5003

### **Radiated emission**



Photo 1




Photo 2

# UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 26 of 27

Issued date : October 3, 2012

Revised date : October 22, 2012

FCC ID : YS34D454C2D5003

### **Worst Case Position**

Below 30MHz Z-axis

Above 30MHz Horizontal: Z-axis / Vertical: Y-axis





Y-axis



**Z**-axis



## UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 27 of 27

Issued date : October 3, 2012

Revised date : October 22, 2012

FCC ID : YS34D454C2D5003

### With/Without Tag



With Tag



Without Tag

#### **End of Report**

# UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN