FCC ID : YS34D454C2D5001 Test report No.: 30LE0268-SH-01-A


Page : 13 of 26


: September 22, 2010 Issued date

APPENDIX 1: Photographs of test setup

Conducted emission

Front view





Side view





UL Japan, Inc. SHONAN EMC LAB.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken 259-1220 JAPAN Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401


FCC ID : YS34D454C2D5001 Test report No.: 30LE0268-SH-01-A


Page : 14 of 26

: September 22, 2010 **Issued date**


Radiated emission








Rear view(9kHz-30MHz)







UL Japan, Inc. SHONAN EMC LAB.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken 259-1220 JAPAN Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401