Test report No.
 : 11834855S-A-R2

 Page
 : 60 of 62

 Issued date
 : March 5, 2018

 FCC ID
 : YSKW80

## **APPENDIX 3:** Photographs of test setup

## **Conducted Emission**






#### UL Japan, Inc. Shonan EMC Lab

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 11834855S-A-R2
Page : 61 of 62
Issued date : March 5, 2018
FCC ID : YSKW80

## **Radiated Spurious Emission**







#### UL Japan, Inc. Shonan EMC Lab

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


Test report No. : 11834855S-A-R2
Page : 62 of 62
Issued date : March 5, 2018
FCC ID : YSKW80

# **Worst Case Position**


X-axis



Y-axis



**Z**-axis



**End of Report** 

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401