Test report No.: 10670940S-A

APPENDIX 3: Photographs of test setup

Conducted emission






UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test report No.: 10670940S-A

Radiated emission







UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401


Test report No.: 10670940S-A

Pre-check of the worst position

X-axis



Y-axis



END OF REPORT

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone : +81 463 50 6400

Telephone Facsimile +81 463 50 6401