Test report No. : 10184718H-A-R1
Page : 54 of 56
Issued date : January 30, 2014
Revised date : February 5, 2014
FCC ID : YSKXW1

# **APPENDIX 3: Photographs of test setup**

### **Conducted Emission**



Photo 1




Photo 2

### UL JapaUL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10184718H-A-R1

Page : 55 of 56
Issued date : January 30, 2014
Revised date : February 5, 2014
FCC ID : YSKXW1

# **Radiated Spurious Emission**



Photo 1




Photo 2

### UL JapaUL Japan, Inc. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124


Test report No. : 10184718H-A-R1
Page : 56 of 56
Issued date : January 30, 2014
Revised date : February 5, 2014
FCC ID : YSKXW1

# Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)

#### X-axis



Y-axis



**Z**-axis



### **End of Report**

### UL JapaUL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124