Test report No.
 : 10833040H-A-R2

 Page
 : 56 of 58

 Issued date
 : June 26, 2015

 Revised date
 : August 27, 2015

 FCC ID
 : YSKA02

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 10833040H-A-R2

 Page
 : 57 of 58

 Issued date
 : June 26, 2015

 Revised date
 : August 27, 2015

 FCC ID
 : YSKA02

Radiated Spurious Emission



Photo 1



Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 10833040H-A-R2
Page : 58 of 58
Issued date : June 26, 2015
Revised date : August 27, 2015
FCC ID : YSKA02

Worst Case Position (Horizontal: Y-axis/ Vertical: Z-axis)

X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124