Test report No. : 30KE0113-YK-01-A-R2

Page : 12 of 43

Issued date : September 30, 2010
Revised date : October 22, 2010
FCC ID : YSKPP1

APPENDIX 1: Photographs of test setup

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 30KE0113-YK-01-A-R2


Page : 13 of 43

Issued date : September 30, 2010 Revised date : October 22, 2010 FCC ID : YSKPP1

Worst Case Position

Below 1GHz (Horizontal: Z-axis/ Vertical: Z-axis) Above 1GHz (Horizontal: Y-axis/ Vertical: X-axis)

X-axis



V-axis

OLYMPUS

OLYMPUS

W



UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124