Test Report No: 10517778S-A

APPENDIX 3: Photographs of test setup

Conducted emission






UL Japan, Inc. **Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone : +81 463 50 6400


Telephone Facsimile +81 463 50 6401

Test Report No: 10517778S-A

Radiated emission



Rear view (below 1GHz)



UL Japan, Inc. **Shonan EMC Lab.**


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone : +81 463 50 6400

Telephone +81 463 50 6401 Facsimile


Test Report No: 10517778S-A

Pre-check of the worst position


X-axis



Y-axis



Z-axis



END OF REPORT

UL Japan, Inc. **Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone : +81 463 50 6400

Telephone Facsimile +81 463 50 6401