

Wireless BedShaker with 520Hz Horn

- Must be linked to Crossfire Smoke, CO or
- Heat alarms to function properly
 Test weekly Press front button
- Replace batteries when alarm chirps and ⚠ flashes red twice per minute
- Silence button will silence alarms for 10 min.

SINGLE AND/OR MULTIPLE STATION SMOKE ALARM ACCESSSORY

90-4066-00



ISSUE NO.

WARNING! Replace batteries with (3) Duracell DL123 only. Use of a different battery can have a detrimental effect on unit's operation.

- This unit is to be installed in a room occupied for sleeping
- Constant exposure to high and low temps or high humidity may reduce battery life
 For more infomation see owner's manual, 90-4072-10
- Serial No: 100001

MFG Date: Feb. 9,2016 Model: CFBS520

For servicing contact: Exigent Sensors LLC 11331 Markon Drive

Garden Grove, CA 92841 USA www.crossfirealarms.com

FCC ID:YST-NX24 This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions:) This device may not cause harmful interference. 2) This cause harmful interference received including interference that a may cause undesired operation

Made in USA

90-4067-00