


EX10 Smoke Alarm Project

Applied Fire Technologies - Multiple Listing Model RF-360TEB

Product Label - Located on underside of alarm



Actual Size



EX10 Smoke Alarm Project

Applied Fire Technologies - Multiple Listing Model EX10AC CAN Product Label - Located on underside of alarm

Material:

Base Material: 3502-17 749 2.6 MIL White BOPP TC S90 40# $\,$

Lamination: 3001-26 10442 1 MIL Clear Compucal EXC MTC722

UL Listing: Ceylon II

Color: Light Gray coated background

HOMEFRONT

Wireless Photoelectric Smoke Alarm with Supplemental Temperature Sensing

• Sensitivity 2.0% +/-1.0% • Heat Sensor Rating: Fixed 135°F (57°C)
• Rate of Rise >15°F/min (8.3°C/min) • Alarm sounds with 3-pulse pattern;
Alarme sonne avec trois sons pulsés • Replace batteries when alarm chirps
and ☐ flashes; Remplacer les piles quand l'alarme chirpe et ☐ clignote
• Service when ⚠ flashes; Entretenir lorsque ⚠ clignote • Silence button will reduce
sensitivity for 10 minutes • Clean alarm by separating halves and vacuuming

• For more detailed information see alarm instruction manual, 90-3021-20; Pour des informations • Test weekly by pressing front button supplementaires voir le manuel

servicing 11331 Markon Drive contact: Garden Grove, CA 92841

Made in USA IC: 9299A-NX13

Note: UL Mark and corresponding information to be printed by UL approved label supplier.

Note: Issue No., MFG Date an Serial No. will change to reflect current conditions. This information to be printed in house.

SISUE NO.
XX,XXXX
S25004

SINGLE AND/OR
MULTIPLE STATION
SMOKE ALARM

EX10AC CAN

Op. Voltage:
120 VAC, 60 Hz
Mfg Date:
Jan 23, 2010
Serial No:
XXXXXX
90

WARNING!
Replace batteries
with (4) Energizer AA
E91 type. Use of a
different battery will
have a detrimental
effect on smoke
alarm operation.
Constant exposure
to high and low

constant exposur to high and low temperatures or high humidity may reduce battery life.

90 301:

Actual Size



EX10 Smoke Alarm Project

Applied Fire Technologies - Multiple Listing Model EX10 CAN Product Label - Located on underside of alarm

Material:

Base Material: 3502-17 749 2.6 MIL White BOPP TC S90 40# $\,$

Lamination: 3001-26 10442 1 MIL Clear Compucal EXC MTC722

UL Listing: Ceylon II

Color: Light Gray coated background

HOMEFRONT

Wireless Photoelectric Smoke Alarm with Supplemental Temperature Sensing

• Sensitivity 2.0% +/-1.0% • Heat Sensor Rating: Fixed 135°F (57°C)
• Rate of Rise >15°F/min (8.3°C/min) • Alarm sounds with 3-pulse pattern;
Alarme sonne avec trois sons pulsés • Replace batteries when alarm chirps
and ☐ flashes; Remplacer les piles quand l'alarme chirpe et ☐ clignote
• Service when ⚠ flashes; Entretenir lorsque ⚠ clignote • Silence button will reduce
sensitivity for 10 minutes • Clean alarm by separating halves and vacuuming

• For more detailed information see alarm instruction manual, 90-3021-20; Pour des informations
• Test weekly by pressing front button

Supplementaires voir le manuel
d'instruction de l'alarme, 90-3021-20

For Exigent Sensors LLC servicing 11331 Markon Drive contact: Garden Grove, CA 92841

Replace by (mth/yr): ____/___ Remplacer par (mois/année):

Made in USA IC: 9299A-NX13

Note: UL Mark and corresponding information to be printed by UL approved label supplier.

Note: Issue No., MFG Date an Serial No. will change to reflect current conditions. This information to be printed in house.



WARNING!

Replace batteries with (4) Energizer AA E91 type. Use of a different battery will have a detrimental effect on smoke alarm operation. Constant exposure to high and low temperatures or high humidity may reduce battery life.

90 30

Actual Size

FCCID: YST-NX13 IC: 9299A-NX13

Label location – Illustration purposes only and may not be the actual label (see previous pages for actual labels)

