

123800\_13.JPG: Test setup fully anechoic chamber


Examiner: Manuel BASTERT
Date of issue: 19 December 2012 Test Report No.: F123800E1 2nd version Order No.: 12-113800

page 1 of 7



page 2 of 7

## ANNEX A TEST SETUP PHOTOS




123800\_05.JPG: Test setup fully anechoic chamber

Test Report No.: F123800E1 2nd version Order No.: 12-113800

Examiner: Manuel BASTERT
Date of issue: 19 December 2012





123800\_12.JPG: Test setup fully anechoic chamber


Examiner: Manuel BASTERT
Date of issue: 19 December 2012 Test Report No.: F123800E1 2nd version Order No.: 12-113800

page 3 of 7



page 4 of 7


## ANNEX A TEST SETUP PHOTOS



123800\_10.JPG: Test setup fully anechoic chamber

Examiner: Manuel BASTERT
Date of issue: 19 December 2012 Test Report No.: F123800E1 2nd version Order No.: 12-113800





123800\_11.JPG: Test setup fully anechoic chamber

Examiner: Manuel BASTERT
Date of issue: 19 December 2012 Test Report No.: F123800E1 2nd version Order No.: 12-113800

page 5 of 7





123800\_1.JPG: Test setup open area test site

Examiner: Manuel BASTERT
Date of issue: 19 December 2012 Test Report No.: F123800E1 2nd version Order No.: 12-113800

page 6 of 7



page 7 of 7

## ANNEX A TEST SETUP PHOTOS



123800\_14.JPG: Test setup outdoor test site

Examiner: Manuel BASTERT Test Report No.: F123800E1 2nd version Order No.: 12-113800

Date of issue: 19 December 2012 Order No.: 12-113800