

Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F181632E4

 Date of issue:
 28.02.2019
 Order Number:
 18-111632

 page 1 of 7
 7





Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F181632E4

 Date of issue:
 28.02.2019
 Order Number:
 18-111632

 page 2 of 7
 7






Test setup – radiated test on open area test site

 Examiner:
 Paul NEUFELD
 Report Number:
 F181632E4

 Date of issue:
 28.02.2019
 Order Number:
 18-111632

 page 3 of 7
 7





Test setup - radiated test on open area test site detail view

 Examiner:
 Paul NEUFELD
 Report Number:
 F181632E4

 Date of issue:
 28.02.2019
 Order Number:
 18-111632

 page 4 of 7
 7






Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F181632E4

 Date of issue:
 28.02.2019
 Order Number:
 18-111632

 page 5 of 7
 7






Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F181632E4

 Date of issue:
 28.02.2019
 Order Number:
 18-111632

Page 6 of 7





Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 F181632E4

 Date of issue:
 28.02.2019
 Order Number:
 18-111632

 page 7 of 7
 7