Test report No.
 : 11123175S-A


 Page
 : 34 of 36


 Issued date
 : February 18, 2016

 FCC ID
 : YUQ-W770MV

APPENDIX 3: Photographs of test setup

Conducted Emission






UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 11123175S-A
Page : 35 of 36
Issued date : February 18, 2016
FCC ID : YUQ-W770MV

Radiated Spurious Emission





1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

 Test report No.
 : 11123175S-A

 Page
 : 36 of 36

 Issued date
 : February 18, 2016


 FCC ID
 : YUQ-W770MV

Worst Case Position

X-axis



Y-axis



Z-axis

End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401