


# Appendix D. Product Photos




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-TSI12 Page Number : D1 of D2
Report Issued Date : Jun. 27, 2011
Report Version : Rev. 01

Report No.: FA151009B



Report No.: FA151009B

### **Antenna Location:**



TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID:

Page Number : D2 of D2
Report Issued Date : Jun. 27, 2011
Report Version : Rev. 01



### Report No.: FA151009B

# Appendix E. Test Setup Photos



**Right Cheek** 










**Left Tilted** 



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

#### SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-TSI12 Page Number : E1 of E1
Report Issued Date : Jun. 27, 2011
Report Version : Rev. 01