


Report No.: FA190327

Appendix D. Product Photos




8 9 10 11 12 13 14 15 16 17

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI12

2

Page Number : D1 of D2
Report Issued Date : Nov. 08, 2011
Report Version : Rev. 02





Antenna location	Length	Width
WWAN (TX/RX)	5.3cm	0.4cm
BT&WLAN(TX/RX)	1.1cm	0.3cm
RFID(TX/RX)	3.7cm	3cm
GPS(RX)	1.6cm	0.4cm

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI12 Page Number : D2 of D2
Report Issued Date : Nov. 08, 2011
Report Version : Rev. 02

Report No.: FA190327



Report No. : FA190327

Appendix E. Test Setup Photos



Right Cheek








Left Cheek

Left Tilted



Front of the DUT with Phantom 1 cm Gap




Back of the DUT with Phantom 1 cm Gap (DUT without Earphone)


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI12 Page Number : E1 of E2
Report Issued Date : Nov. 08, 2011
Report Version : Rev. 02






Back of the DUT with Phantom 1 cm Gap (DUT with Earphone)




Report No.: FA190327


Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI12

Page Number : E2 of E2 Report Issued Date: Nov. 08, 2011 Report Version : Rev. 02