

Appendix D. Product Photos




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11 Page Number : D1 of D2
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01

Report No.: FA181934



Report No.: FA181934

Antenna Location:




Antenna location	Length	Width
WWAN Antenna <tx rx=""></tx>	5.8cm	0.8cm
Bluetooth & WLAN Antenna <tx rx=""></tx>	2.3cm	0.4cm

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11 Page Number : D2 of D2
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01



Report No.: FA181934

Appendix E. Test Setup Photos





Right Cheek


Right Tilted






Left Cheek

Left Tilted



Front of the DUT with Phantom 1 cm Gap (DUT with Earphone)




Front of the DUT with Phantom 1 cm Gap (DUT without Earphone)


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11 Page Number : E1 of E2
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01






Back of the DUT with Phantom 1 cm Gap (DUT with Earphone)




Report No.: FA181934


Back of the DUT with Phantom 1 cm Gap (DUT without Earphone)




Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11

Page Number : E2 of E2 Report Issued Date: Oct. 19, 2011 Report Version : Rev. 01