

Report No. : FA391350

Appendix D. SAR Test Setup Photos





Right Cheek

Right Tilted





Left Cheek

Left Tilted

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-301F Page Number : D1 of D2
Report Issued Date : Oct. 28, 2013


Report Version : Rev. 01



Report No.: FA391350

Front, Test Separation 1 cm

Back, Test Separation 1 cm







Top Side, Test Separation 1 cm



Right Side, Test Separation 1 cm



Left Side, Test Separation 1 cm

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-301F Page Number : D2 of D2
Report Issued Date : Oct. 28, 2013
Report Version : Rev. 01