
3. Internal Photograph of EUT


Brand Name: Fujitsu Toshiba Mobile Communications Ltd. / Model Name: FJI11

Report No.: EP181934



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11 Page Number : 6 of 14
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11 Page Number : 7 of 14
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01

Report No.: EP181934



Brand Name: Fujitsu Toshiba Mobile Communications Ltd. / Model Name: FJI11 8 30 րտելչ համասնամարդիանչ չերը կանանախանդիր համարանականում ավային կանկանի կանկանի կա OU T 06 08 09 01 30


Report No.: EP181934

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11


: 8 of 14 Page Number Report Issued Date : Oct. 19, 2011 Report Version : Rev. 01

Report No.: EP181934




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11 Page Number : 9 of 14
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01

Report No.: EP181934



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11 Page Number : 10 of 14
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01

Report No.: EP181934



Brand Name: Fujitsu Toshiba Mobile Communications Ltd. / Model Name: FJI11


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11 Page Number : 11 of 14
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01

Report No.: EP181934




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11 Page Number : 12 of 14
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01

Report No.: EP181934



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11 Page Number : 13 of 14
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01

Report No.: EP181934



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YUW-FJI11 Page Number : 14 of 14
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01