

Label 1

- All labels should use THT B422 material from Brady or similar.
- UL recognized or listed. RoHS compliant.
- Appropriate for use outdoors.
- WEE compliant.

Label 2

• Same as label 1.

Label position:

The labels are places at the bottom of the sensor enclosure. See the assembly Drawing excerpt on next page.

