

Report No.: FA092013

Appendix D. Product Photos



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YWE-DLI8400 Page Number : D1 of D1
Report Issued Date : Dec. 15, 2010
Report Version : Rev. 01



Report No.: FA092013


Appendix E. **Test Setup Photos**



Primary Landscape



Primary Portrait



Bottom of the DUT

Secondary Portrait

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YWE-DLI8400 Page Number : E1 of E1 Report Issued Date: Dec. 15, 2010 Report Version : Rev. 01