


## Appendix A. Setup Photographs

<Radiated Emission>


**EUT with Battery 1** 

**Z** Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YY3-NX1UMTS Page Number : A1 of A4 Report Issued Date: Jan. 20, 2014

**Report No.: FG342939** 

Report Version : Rev. 01




Report No. : FG342939


## **EUT with Battery 2**

Z Plane

LF



## HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YY3-NX1UMTS Page Number : A2 of A4
Report Issued Date : Jan. 20, 2014
Report Version : Rev. 01




**Report No.: FG342939** 


## **EUT with Battery 1**

Y Plane

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YY3-NX1UMTS Page Number : A3 of A4
Report Issued Date : Jan. 20, 2014
Report Version : Rev. 01






**EUT with Battery 2** 

Y Plane

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YY3-NX1UMTS Page Number : A4 of A4
Report Issued Date : Jan. 20, 2014
Report Version : Rev. 01

**Report No.: FG342939**